AltiGen KB

MaxCS 8.5.1 Deployment Guide

Updated 7/16/19 - Changes to the Requirements section.
Updated 1/29/19 - Added support for Windows Server 2016.
Updated 6/21/18 - Added note that port 5061 must be open.
This document is provided for AltiGen partners who will be performing a fresh installation of MAX Communication Server (MaxCS) Release 8.5 Update 1 All-Software Softswitch Solution for their clients. IMPORTANT! These instructions are only for new installations of MaxCS. If you are upgrading from a previous release of MaxCS, follow the instructions in the MaxCS 8.5 Update 1 Upgrade Guide instead.

https://know.altigen.com/questions/1253/