

Polycom UC Version and Supported BTOE Version

This article describes the supported BTOE (Better Together over Ethernet) versions for Polycom firmware.

Firmware	BTOE 2.3.0	BTOE 3.7.0	BTOE 3.7.5	BTOE 3.8.0	BTOE 3.9.0
5.6.3	Auto Pairing Manual Pairing	Auto Pairing	Auto Pairing	Not Supported	Not Supported
5.7.4	Auto Pairing	Auto Pairing Manual Pairing	Auto Pairing Manual Pairing	Not Supported	Not Supported
5.8.2	Not Supported	Not Supported	Not Supported	Auto Pairing Manual Pairing	Auto Pairing Manual Pairing
5.9.1	Not Supported	Not Supported	Not Supported	Auto Pairing Manual Pairing	Auto Pairing Manual Pairing

BTOE Download Links:

Version 3.7.0	https://tsfiles.altigen.com/main.html?download&weblink=9e395fede06daa6d66c46f2fa921ea7e&realfilename=
Version 3.7.5	https://tsfiles.altigen.com/main.html?download&weblink=05ee4357cc44226838c0bead43adcc7b&realfilename=
Version 3.8.0	https://tsfiles.altigen.com/main.html?download&weblink=22b535d7f6a869fc8ce1e4c6060f1c09&realfilename=
Version 3.9.0	https://tsfiles.altigen.com/main.html?download&weblink=ebb0d433594ddde1c1850add1a3a7ef&realfilename=

<https://know.altigen.com/questions/1272/>